WEATHERING DETERIORATING AND SLOPE STABILITY CLASSIFICATION FOR THE FUTURE

Robert Hack

Geo-Engineering, ESA, International Institute for Geoinformation Sciences and Earth Observation (ITC) The Netherlands

Namur, Belgium, 12 June 2008



Slopes in The Netherlands?



Namur, Belgium - weathering deteriorating slope stability future - Robert Hack

van Goyen, View at Leiden, 1650 – Museum Lakenhal, Leiden

Dykes have slopes!





Namur, Belgium - weathering deteriorating slope stability future - Robert Hack

PUTTIN

Also real rock slopes in the



Namur, Belgium - weathering deteriorating slope stability future - Robert Hack

ІТС

Other reasons to study slopes even if coming from a flat country

Slopes are an ideal study object for soil and rock mechanics in general because:

- Soil or rock in tunnels and foundations often not visible
- Failures in tunnels or foundations not or difficult to study
- Slopes often easily accessible
- Often many slopes in a relatively small area



and not very scientific, but highly important:

many Dutch civil engineering companies work worldwide with soil and rock slopes



Slope stability



What is required to analyse the stability of a slope ?

- soil and rock mass properties
- present and future geometry
- present and future geotechnical behaviour of soil or rock mass
- external influences such as earthquakes



Slope stability analyses done per geotechnical unit in a geometrically uniform slope geometry, e.g. a slope analyses is done for a uniform material with uniform geometry

Is that possible ?

Variation

Heterogeneity of mass causes:variation in mass properties


Heterogeneity of slope geometry causesVariation in geometry



Original situation



design error



Example 2: Many discontinuity sets with large variation in orientation (too many for the design engineer?)

Example 3: Many discontinuit sets with large variation in orientation

Example 4. Variation in clay content in intact rock causes differential

weathering

Slightly higher clay content

bedding planes

Example 4: Variation in clay content in intact rock causes differential weathering

ril 1992



Uncertainty

- Uncertainty in properties
- Uncertainty (error) in measurements of properties
- Uncertainties in geometry
- Uncertainty (error) in measurements of geometry (often small)
- Uncertainty in failure mechanisms applicable
- Uncertainty in future environment (for example, weathering)



Options for analysing slope stability

Analytical Numerical Classification



Analysing slope stability

- analytical: only in relatively simple cases possible for a discontinuous rock mass
- numerical: difficult and often cumbersome, however, possible with discontinuous numerical rock mechanics programs such as UDEC

Hence, classification systems may be a good and simple alternative



Classification systems are empirical relations that relate rock mass properties either directly or via a rating system to an engineering application, e.g. a slope



Existing classification systems:

For underground tunnels:

Bieniawski (RMR) Barton (Q) Laubscher (MRMR) etc.

For slopes:

Selby Bieniawski (RMR) Vecchia Robertson (RMR) Romana (SMR) Haines etc. etc.



Development of existing rock mass classification systems

- First developed for underground excavations
- Most slope systems are based on underground systems adjusted to be used for slopes

Existing systems did not give satisfactory results – hence development of a new system



Slope Stability probability Classification (SSPC)




SSPC

- three step classification system
- based on probabilities
- Independent failure mechanism assessment



Three step classification system (1)



1: natural exposure made by scouring of river, moderately weathered; 2: old road, made by excavator, slightly weathered; 3: new to develop road cut, made by blasting, moderately weathered to fresh. Excavation specific parameters for the excavation which is used to characterize the rock mass

- Degree of weathering
- Method of excavation



Rock mass Parameters

- Intact rock strength
- Spacing and persistence discontinuities
- Shear strength along discontinuity
- Roughness large scale
 - small scale
 - tactile roughness

- Infill
- Karst
- Susceptibility to weathering



Slope specific parameters for the new slope to be made

- Expected degree of weathering at end of lifetime of the slope
- Method of excavation to be used for the new slope



Intact rock strength

By simple means test - hammer blows, crushing by hand, etc.




Spacing and persistence of discontinuities

Based on the block size and block form by first visual assessment and then quantification of the characteristic spacing and orientation



roughness





Infill:

- cemented
- no infill
- non-softening (3 grain sizes)
- softening (3 grain sizes)
- gauge type (larger or smaller than roughness amplitude)
- flowing material

Shear strength - Infill



Orientation dependent stability

Stability depending on relation between slope and discontinuity orientation


- Instability caused by discontinuities


Orientation independent stability

Stability not depending on relation between slope and discontinuity orientation

 Instability not caused by discontinuities (for example, failure of intact rock, water run off moving blocks from the slope, etc.)







Poorly blasted slope




New cut (in **1990**):

- Visual assessed: extremely poor instable.
- SSPC stability < 8% (13.8 m high, dip 70°, rock mass weathering:
- 'moderately' and 'dislodged blocks' due to blasting).
- Forecast in **1996**: SSPC stability: slope dip 45°.
- In **2002**: Slope dip about 55° (visually assessed unstable).
- In **2005**: Slope dip about 52° (visually assessed unstable big blocks in middle photo have fallen).



Plane sliding failure

40 year old road cut, Spain



Plane sliding failure (2)



- Laboratory test: φ=45°
- SSPC: φ≈35°
- Stability assessed using:
 - SSPC 55% stability probability, failure imminent (\$<35°)



Landslide in harbour – Saba – Dutch Antilles





SSPC results

Pyroclastic deposits

Rock mass friction Rock mass cohesion Calculated maximum possible height on the slope **Calculated SSPC** 35° 39kPa 13m

Laboratory / field 27° (measured) 40kPa (measured) 15m (observed)



Failing slope in Manila, Philippines



ITC




Failing slope in Manila (2)

- tuff layers with near horizontal weathering horizons (about every 2-3 m)
- slope height is about 5 m
- SSPC non-orientation dependent stability about 50% for 7 m slope height
- unfavourable stress configuration due to corner




Exposure 1-5 - photo 37 (view direction 285°

Widening existing road in Bhutan (Himalayas)






Bhutan (5) Method of excavation






Widening existing road in Bhutan (Himalayas) (2)





Widening existing road in Bhutan (Himalayas) (4)



Above road level:

 Following SSPC system about 12 – 27 m for a 75° slope (depending on unit) (orientation independent stability 85%)

Below road level:

Inaccessible – different unit ? – and not disturbed by excavation method




Heterogeneity

- even if uncertainty is included this is only up to a certain extend – what extend is to the discretion of the engineer
- can heterogeneity be defined by an automatic procedure, e.g. for example Lidar



Heterogeneity – Lidar imagery





(modified after Slob et al, 2002)

Degradation processes

Main processes involved in degradation:

- Loss of structure due to stress release
- Weathering (In-situ change by inside or outside influences)
- Erosion (Material transport with no chemical or structural changes)




Significance in engineering

 When rock masses degrade in time, slopes and other works that are stable at present may become unstable





Weathering rates



ITC

Weathering rates

$$WE(t) = WE_{init} - R_{WE}^{app} \log(1+t)$$

WE(t) = degree of weathering at time t $WE_{init} = (initial)$ degree of weathering at time t = 0 $R^{app}_{WE} =$ weathering intensity rate

WE as function of time, initial weathering and the weathering intensity rate



Weathering rates

Material:
Gypsum layers
Gypsum cemented siltstone layers

Middle Muschelkalk near Vandelles (Spain)

Weathering intensity rate

SSPC system with applying weathering intensity rate:

- original slope cut about 50° (1998)
- now around 44° (2007)
- in 15 years decrease to 35° (2013)






New developments - Future





Remote sensing for assessing "degree of weathering"



Namur, Belgium - weathering deteriorating slope stability future - Robert Hack

ITC

Conclusions

- SSPC classification works for slope stability
- Classification can incorporate uncertainty
- Rates of weathering can likely be quantified

 be not afraid to abandon inherited methodologies and parameters



Future

- more objective (remote sensing) tools to determine heterogeneity and degree of weathering
- classification systems for earthquake areas
- Influence of snow and ice
- submersed marine slopes ?

